

Tel-Instrument has posted a Technical Bulletin covering the T-47/M5, TS-4530A and T-4530i IFF Test Sets. The TB details a growing issue with legacy GPS modules which may impact your test set. Please navigate to the Service Bulletins - General Information menu page to download a copy of the Technical Bulletin and further information or click below to go to the page directly:

[Service Bulletin - General Information](#)